


IPS Hot Surface Igniters

- Includes 3 brackets, wire sleeving, mounting screw, 2 wire nuts, cross reference list, and instruction sheet
- 14" leads


67900
Furnace Igniter Kit



• Replacement for flat and spiral igniters in over 50 furnace applications

- 19" leads with sleeving and connector


67909



REPLACES:
• Coleman 1474-051P, 052P

- Gasket included
- 5.5" leads with connector


67914



REPLACES:
• Amana 1004 1601, B1336102, D99182
• Trianco-Heatmaker 2600-359 • Uni-Line 41-401
• White Rodgers 767A-309, 767A-356

- 19" leads with wire nuts


67915



REPLACES:
• Armstrong 38322B001 • Clare C-238, C-242
• DMO 20834, 26789 • Dornback 271W
• Rheem 62-55774-01 • Trane 340039P01, IGN23
• Uni-Line 41-238, 41-242, 41-402
• White Rodgers 767A-371 • Williamson 09050

- 5.5" leads with wire nuts


67916



REPLACES:
• Raypak 600915 • Snyder General 1380654 • Trane B138196P01, IGN26, IGN30, Uni-Line 41-403
• Well McLain 511-330-193

- 5.5" leads with wire nuts


67917



REPLACES:
• Uni-Line 41-405 • White Rodgers 767A-361 • York 025-27766-000, 025-27774-000, 025-29043-000, 025-29050-000

- 5.5" leads with connector


67918



REPLACES:
• Trane B144676P02, IGN30 • Uni-Line 41-407

- 5.5" leads with connector


67919



REPLACES:
• Rheem 62-22868-92, 62-22868-93 • Trane B340039P01 • Uni-Line 41-408

- 5.5" leads with connector

67920



REPLACES:
• Carrier LH33ZS001, 002, 003, 004 • Ducane 20015201 • Snyder General 1380672, 1380680
• Trane IGN26 • Uni-Line 41-409
• Weil McLain 511-330-139

- 36" leads with sleeving and connector


67921



REPLACES:
• Lennox 33J37

- 5.5" leads with connector


67923



REPLACES:
• York 025-32625-000

- 5.5" leads with connector
- Mounting bracket attached


67924



REPLACES:
• Goodman B1401015, B1401018S
• Modine 5H075032B

- 11" leads with wire nuts
- Gasket included


67925



REPLACES:
• Glowcore HSRK-7 • Lochinvar PLT2400
• Surfaceigniter FY009 • Uni-Line 41-406
• Weil-McLain 511-330-188 • White Rodgers 767A-374

- 5.5" leads with connector
- Bracket included


68013



REPLACES:
• Rheem 62-22868-82 • Uni-Line 41-411

- 5.5" leads with connector
- Bracket included


68014



REPLACES:
• Goodman B1401009 • Intercity 1009604
• Uni-Line 41-412

- 8.5" leads with connector
- Mounting bracket and gasket included


68015



REPLACES:
• Rheem 62-22669-92

- 5.5" leads with connector

68016



REPLACES:
• Trane B144676P02, IGN30 • Uni-Line 41-410

- 5.5" leads with connector

68017



REPLACES:
• Uni-Line 41-404
• Weil McLain 511-330-190